



Original CR

Metro Phoenix Auto Auction
2475 S. 59th Avenue
Phoenix, AZ 85043
602-279-9500
remst@metroaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2008 CHEVRO UPLANDER LS**
Bodystyle/Series: **4 Door Vehicle -**
Color: **WHITE**
Mileage: **26,572 (Verified, 6 digits)**
Turn-in Mileage: **-**
VIN: **1GNDV23W28D183167**
Work Order/ **000633819**
Stock Number:
Customer:

GSA Fleet Vehicle Sales
1800 F Street NW
Room 3400
Washington, DC 20405
417-276-3475
linda.betlock@gsa.gov

Client Stock #: **G411736G**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev.
Repair Order: **-**



Drivable: Yes	Tire Rating: null	Incremental Recon: No
---------------	-------------------	-----------------------

UniBody/Frame Damage: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.9 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /Gray	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	0	Brakes:	Power Brakes


Additional Equipment:

Air Conditioning	LF Tires - 7/32 inch	RF Tires - 7/32 inch
LR Tires - 7/32 inch	RR Tires - 7/32 inch	Car Tire Size - RR SIDE TIRE SIZE 17


Car Tire Size - LR SIDE TIRE SIZE 17	Car Tire Size - LF SIDE TIRE SIZE 17	Car Tire Size - RF SIDE TIRE SIZE 17
Rear AC	Tire Brand - Front Left - LF SIDE TIRE MFG Bridgestone	Tire Brand - Front Right - RF SIDE TIRE MFG Bridgestone
Tire Brand - Rear Left - LR SIDE TIRE MFG Bridgestone	Tire Brand - Rear Right - RR SIDE TIRE MFG Bridgestone	ABS Brakes
Power Antenna	Power Mirrors	Rear Wiper
CD in Dash	Front Wheel Drive	Power Windows
Power Lock	Tilt Wheel	Power Steering
Cruise Control		

Non Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Photo - Rear	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
[no photo]	Photo - Wheel	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Interior	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Rear	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Extra Photo 1	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
[no photo]	Photo - Interior	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown

	Photo - Left	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
				\$0.00 (total)	\$0.00 (total)	0 (total)	0 (total)	\$0.00 (total)		

Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Front Emblem	Rusty	-	\$0.00	\$150.00	0	0	\$150.00	Report	Unknown
	Rear Bumper	Dents W/ Paint Dmg	-	\$0.00	\$300.00	0	0	\$300.00	Report	Unknown
	Left Front Tire	Ok	-	\$0.00	\$0.00	0	0	\$0.00	Report	Unknown
	Left Rear Tire	Ok	-	\$0.00	\$0.00	0	0	\$0.00	Report	Unknown
	Right Rear Tire	Ok	-	\$0.00	\$0.00	0	0	\$0.00	Report	Unknown
	Right Front Tire	Ok	-	\$0.00	\$0.00	0	0	\$0.00	Report	Unknown
				\$0.00 (total)	\$450.00 (total)	0 (total)	0 (total)	\$450.00 (total)		

File Insurance Claim? No

Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.